Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	44	123/46h.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/27 12:13
L2	17	1 and meter\$3	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/27 12:44
L3	751	123/299.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/27 12:44
L4	1	3 and (setting with tool)	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/27 12:44
L5	148	3 and meter\$3	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/27 12:44
L6	785	227/10.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/27 12:44
L7	106	6 and meter\$3	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/27 12:44
L8	26	7 and (setting with tool)	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/27 12:45
L9	98	7 and (combustion with chamber)	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/27 12:45
S1	102	123/460.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/26 20:37
S2	0	S1 and (setting with tool)	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/27 12:44
S3	880	"setting tool"[ti]	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/09/20 02:36

S4	256	S3 and fasten\$3	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/26 20:38
S5	4	S4 and engine	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/09/20 02:37
S6	43	S4 and (combustion with chamber)	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/27 12:45
S7	36	S6 and fuel	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/09/20 02:37
S8	17	S7 and meter\$3	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/27 12:13
S9	9	S8 and sensor	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/26 20:38
S11	44	123/46h.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/26 20:37
S12	9	S11 and (setting with tool)	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/26 20:38
S13	8	S12 and (combustion with chamber)	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/26 20:38
S14	-8	S13 and fasten\$3	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/26 20:38
S15	6	S14 and meter\$3	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/26 20:38
S16	3	S15 and sensor	US-PGPUB; USPAT; USOCR; EPO; JPO	OR	ON	2005/12/26 20:39